



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:					
Company	Dennis Ware Controller				
Company	Steve Demczak Environmental Scientist III				

Inspection Report

Permit Number:	C0070006
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, April 27, 2010
Start Date/Time:	4/27/2010 2:00:00 PM
End Date/Time:	4/27/2010 4:00:00 PM
Last Inspection:	Tuesday, March 23, 2010

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's, Windy InspectionID Report Number: 2343

Types of Operations

Accepted by: ihelfric

5/6/2010

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	8,919.91	
Total Disturbed	113.34	
Phase I	113.34	
Phase II	95.30	
Phase III	5.64	

Mineral Ownership

✓ Federal ✓ Underground State ☐ Surface County ☐ Loadout

✓ Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Monday, May 03, 2010

Date

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 27, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		✓	
2.	Signs and Markers	V		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.l	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		V	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 27, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permittee has submitted a Phase III bond release for a section of land for gas drilling by Conoco Philips.

2. Signs and Markers

The identification signs is next to the road to the site.

3. Topsoil

All topsoil was used for reclamation.

4.a Hydrologic Balance: Diversions

Diversions were inspected and were functioning as designed.

8. Noncoal Waste

The reclaim site is clear of non-coal waste material.

12. Backfilling And Grading

No slides were noticed during the inspection.

18. Support Facilities, Utility Installations

There are no facilities.